

TSP Name / TSP: DOMINION GATHERING & PROCESSING, INC. (80303417)
Critical: Y
Notice Eff Date: 12/19/2016 Posting Date: 12/19/2016
Notice Eff Time: 10:20 PM Posting Time: 10:20 PM
Notice Stat Desc: Initiate Notice ID: 185415
Notice Type Desc: Maintenance Prior Notice: 0
Regrd Rsp Desc: No response required
Response Date:
Response Time:

Subject: Hastings Extraction Plant Unplanned Outage - Production Shut-In

Notice Text:

Dominion Gathering and Processing (DGP)'s Hastings Extraction Plant is currently out of service for unplanned maintenance.

Effective immediately, all gathering wet system production and direct taps feeding into Dominion Transmission (DTI)'s wet system flowing to Hastings must be shut-in until further notice. Gathering production feeding Lightburn Extraction Plant will not be shut-in if such production can continue to flow. DGP has determined that only certain Bubbles can physically flow to Lightburn during this outage due to system constraints.

Those Bubbles are listed below. DGP will monitor field pressures in order to preserve system integrity and may need to adjust flows from Bubbles during the outage.

DGP will make another posting when production can be turned back in-line.

See Details Below:

Stations to be shut-in during this outage are: Big Isaac, Bogal, Chapman, Collins, Cornwell 7, 8 & 9, Craig, Deep Valley, Hastings Station, Jones, Maxwell, New Oxford, Orma, Schutte, Smithburg, South Oxford, Sutton, Law, Chapman, Wilsonburg, Sardis and Yellow Creek.

Bubbles to be shut-in during this outage are: 2206, 2207, 3201, 3202, 3203, 3204, 3205, 3206, 3207, 3208, 3209, 3210, 3211, 3212, 3213, 3214, 3215, 3216, 3217, 3218, 3219, 3220, 3221, 3222, 3223, 3224, 3225, 3226, 3227, 3303, 4201, 4401, 4402, 4403, 4404, 4405, 4406, 4407, 4408, 4409, 4410, 4411 and 4413.

Stations that will remain in service and feed to Lightburn Extraction Plant are: Keith Fork, Kennedy, Davis, Camden, Weston.

Direct Taps to remain in service are: Copley and Mountaineer.

Bubbles that will remain in service and feed Lightburn Extraction Plant are: 3301, 3302, 3304, 3305, 3306, 3307, 3401, 3402, 3403, 3404, 3405, 3406, 3407, 3408, 3409, 3410, 3411, 3412, 3413, 3414, 3415.

Producers that are remaining in service during this outage may notice higher than normal line pressure. DGP will continue to monitor pressure and if pressures become too high, production shut-ins may become necessary.

Delivery nominations during this period from Pods 1-10, and 14 will be kept whole by DTI.

Delivery nominations during this period from EB120, EB130, EB145, EB170, EB210, EB370, EB380, EB455, EB470, EB560, EB565, EB610, EB615, EB640, EB645, EB655 and EB660 will be kept whole by DTI.

Please continue to monitor these postings for updates.